

Technical Specifications

	Bluelab Soil pH Meter
Range	0 - 14 pH
Resolution	0.1 pH
Accuracy (at 25°C)	± 0.1 pH
Temperature Compensation	Not applicable
Operating Temperature Range	0 - 45°C 32 - 113°F
Power Source	2 x AAA Alkaline batteries
Calibration	Manual calibration
Other Features	Low battery warning Auto turn off function Over range and under range indicators